

Session: Steel 1



The Details We Left Behind

Michael D. Engelhardt
Dept. of Civil, Architectural and Environmental Engineering
University of Texas at Austin

January 16-17, 2014 - University of California, Los Angeles

Overview





- Review of “Pre-Northridge” steel moment connection.
- A brief history of research and code adoption.
- Examples of damage observed following Northridge Earthquake.
- Observations




Steel Moment Resisting Frame

Pre-Northridge Beam-to-Column Connections for Steel Moment Resisting Frames





“Steel Connections/Details and Relative Costs” 1986



Typical Pre-Northridge Welded Flange-Bolted Web Moment Connection



Code Provisions Prior to 1994

1982 UBC

“Each beam or girder moment connection to a column shall be capable of developing in the beam the full plastic capacity of the beam or girder.”

Code Provisions Prior to 1994

1988 UBC

Required Strength: The girder to column connection shall be adequate to develop the lesser of the following:

- i. The strength of the girder in flexure.
- ii. The moment corresponding to development of the panel zone shear strength as determined from Formula (22-1).

Code Provisions Prior to 1994

1988 UBC (cont)

The girder to column connection may be considered adequate to develop the flexural strength of the girder if it conforms to the following:

- i. The flanges have full penetration butt welds to the columns.
- ii. The girder web to column connection shall be capable of resisting the girder shear determined for the combination of gravity loads and the seismic shear.....


Research and Testing Prior to 1994

“Cyclic Loading of Full-Size Steel Connections”


E.P. Popov and R.M. Stephen

AISI Bulletin 21, 1972


- **Tests conducted at UC Berkeley ~1970**
- **Tests on W18x50 and W24x76 beams**
- **Tests compared all-welded connections with welded flange-bolted web connections**




W24 x 76 WELDED
 JOINT DETAIL





SECTION A-A




All-Welded Detail



24 WF 76
ALL WELDED



**W24 x 76 BOLTED
 JOINT DETAIL**



Welded Flange – Bolted Web Detail




W24 x 76 -- 7-1" BOLTS

Research and Testing Prior to 1994



Subsequent test programs...












Tests on Large-Scale Welded Flange - Bolted Web Connections 1970-1992



Damage to Steel Moment Connections in the 1994 Northridge Earthquake












1M3 E BF








1 1/2 INCH 2 3

BF

A photograph showing a close-up of a concrete structure. A yellow ruler is placed horizontally across the top of the concrete. Below the ruler, a white label with a blue border is attached to the concrete. The label contains the text "PL-6L-N-BF". The concrete surface is rough and appears to be part of a larger structure, possibly a wall or ceiling. There are some dark spots and a crack visible in the concrete. The lighting is somewhat dim, and the overall color palette is dominated by the grey and brown tones of the concrete and the yellow of the ruler.

1 2
PL-6L-N-BF





Factors Contributing to Moment Connection Damage in Northridge

- Welding
- Design
- Materials

Observations

- No steel moment frame buildings collapsed – no loss of life.
- Response to damage - SAC and other research efforts:
highly effective collaboration between profession, industry, academia, and government.

Observations

- Northridge moment connection damage ultimately led to a much better understanding of seismic response of steel structures.