



# The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps

January 16-17, 2014  
Los Angeles, CA

## Revisiting W1 Indications

Duane K. Miller, Sc.D, P.E.





**MISSION**  
**IMPOSSIBLE**



# **The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps**

January 16-17, 2014  
Los Angeles, CA

## **Revisiting W1 Indications**

**How W1s mislead many in  
the aftermath of Northridge...  
...and continue to do so today.**



# The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps


January 16-17, 2014  
Los Angeles, CA

---


## Revisiting W1 Indications

### W1s: What Are They?

## Figure 2b. Survey form Section V damage types.



## Figure 2b. Survey form Section V damage types.



## Figure 2c. Form Section V damage types, continued.





Figure 2c. Form Section V damage types, continued.





# 94-01 SAC Invitational Workshop on Steel Seismic Issues




Figure 2a. Survey form Section V damage description page.

**SURVEY OF STEEL MRF BUILDINGS**  
**DAMAGED BY THE NORTHRIDGE EARTHQUAKE,**  
**JANUARY, 1994**

FLOOR \_\_\_\_\_ FRAME \_\_\_\_\_

Building: \_\_\_\_\_  
 Engineer: \_\_\_\_\_  
 Firm: \_\_\_\_\_  
 Date: \_\_\_\_\_ Page: \_\_\_\_\_


Flange	W1	Incipient weld crack
Weld	W2	Full or partial crack through weld metal
Damage	W3	Fracture at girder interface
	W4	Fracture at column interface

	C5	Lamellar flange crack	<input type="checkbox"/> 5518Xx	<input type="checkbox"/> 5519Xx
Flange	W1	Incipient weld crack	<input type="checkbox"/> 5520Xx	<input type="checkbox"/> 5521Xx
Weld	W2	Full or partial crack through weld metal	<input type="checkbox"/> 5522Xx	<input type="checkbox"/> 5523Xx
Damage	W3	Fracture at girder interface	<input type="checkbox"/> 5524Xx	<input type="checkbox"/> 5525Xx
	W4	Fracture at column interface	<input type="checkbox"/> 5526Xx	<input type="checkbox"/> 5527Xx
Shear	S1	Weld crack at column (welded web only)	<input type="checkbox"/> 5528Xx	<input type="checkbox"/> 5529Xx
Connection	S2	Weld crack at shear tab	<input type="checkbox"/> 5530Xx	<input type="checkbox"/> 5531Xx
Damage	S3	Crack in girder web or shear plate through bolt holes	<input type="checkbox"/> 5532Xx	
	S4	Plastic deformation of web or plate at bolt holes	<input type="checkbox"/> 5533Xx	
	S5	Loose, damaged, or missing bolts	<input type="checkbox"/> 5534Xx	
Panel	P1	Damage to continuity plate	<input type="checkbox"/> 5535Xx	<input type="checkbox"/> 5536Xx
Zone	P2	Crack in continuity plate weld	<input type="checkbox"/> 5537Xx	<input type="checkbox"/> 5538Xx
Damage	P3	Damage to doubler plate	<input type="checkbox"/> 5539Xx	
	P4	Crack in doubler plate weld	<input type="checkbox"/> 5540Xx	
	P5	Partial depth crack in column web (extension of C3)	<input type="checkbox"/> 5541Xx	<input type="checkbox"/> 5542Xx
	P6	Full (or near full) depth crack in column web	<input type="checkbox"/> 5543Xx	<input type="checkbox"/> 5544Xx

Provide additional descriptions of MRF joint damage as appropriate: \_\_\_\_\_ 5545Xx

\_\_\_\_\_

\_\_\_\_\_



**W1 Incipient weld crack**

# PROCEEDINGS

of  
AISC Special Task Committee  
on the Northridge Earthquake  
Meeting

March 14-15, 1994


## PROCEEDINGS

of  
AISC Special Task Committee  
on the Northridge Earthquake  
Meeting  
March 14-15, 1994



AISC, Inc.  
One East Wacker  
Suite 3100  
Chicago, IL 60601  
312/670-2400


# PROCEEDINGS of AISC Special Task Committee on the Northridge Earthquake Meeting



## DAMAGE TO DUCTILE STEEL FRAMES IN THE NORTHRIDGE EARTHQUAKE

Examination of a few damaged welds reveals that **only half of the bottom flange has cracked**. In addition, **some welds appear to have been cracked prior to the earthquake**. These cracks have been identified through the presence of **rust in the weld crack**.

# PROCEEDINGS of AISC Special Task Committee on the Northridge Earthquake Meeting



## SUMMARY REPORT

Appropriate action must be taken to improve the observed performance, especially wherein a high **60-80% connection failure rate occurred in some moment frames.**



# **The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps**

January 16-17, 2014  
Los Angeles, CA

---

## **Revisiting W1 Indications**


**W1s: What Caused Them?  
(early thoughts)**


# Invitational Workshop on Steel Seismic Issues

Los Angeles, CA

September 8-9, 1994

SAC 94-01






## WELDING AND MECHANIAL PROPERTIES OF WELDS

### Preheat, Cooling Rates and Postheat

It was noted that evidence of pre-existing cracks, especially in the root of the welds, had been detected in many of the damaged SMRF connections. This could have easily been the result of inadequate preheat.






## WELDING AND MECHANIAL PROPERTIES OF WELDS

### Preheat, Cooling Rates and Postheat


It was acknowledged that structural steel erectors do not closely adhere to good preheat practices, and that increased monitoring to ensure minimum uniform preheats are properly applied is imperative.



## WELDING AND MECHANIAL PROPERTIES OF WELDS

### Preheat, Cooling Rates and Postheat


It was suggested that hardness in the Heat Affected Zone (HAZ) could have played a significant role in the failure mechanism of weld in the Northridge earthquake. High hardness could have reduced toughness, increased a hydrogen embrittlement problem, and reduce ductility of the HAZ.



## WELDING AND MECHANIAL PROPERTIES OF WELDS

### Preheat, Cooling Rates and Postheat


For repair work, it was agreed that an increase of 100 degrees Fahrenheit above the minimum required preheat temperature required by AWS D1.1 for a given material and thickness should be adopted as an inexpensive way to mitigate the initiation of cracking during the repair of damaged SMRF connections.



## WELDING AND MECHANIAL PROPERTIES OF WELDS

### Preheat, Cooling Rates and Postheat


Slow cooling with insulating blankets was considered to be worthwhile to diffuse hydrogen.



## WELDING AND MECHANIAL PROPERTIES OF WELDS

### Preheat, Cooling Rates and Postheat


The use of Dehydrogenation Heat Treat (DHT) for thicker joints was considered to be worthwhile, and a recommendation was made to use 450 degrees Fahrenheit for one hour per inch of thickness, when the weld joint exceeds 1”.



## WELDING AND MECHANIAL PROPERTIES OF WELDS

### Welding Electrodes


It was agreed that the SMAW E7018 low hydrogen electrode was the most reliable and exhibited the best properties under field conditions.



## **SURVEY OF DAMAGE—Preliminary Report**

### **Background**

As of September 1994, eight months after the earthquake, the estimate has grown to **over 100 damaged MRF buildings....**



## THE SAC STEEL PROGRAM

### The Problem

Among the many issues discussed...there are **six main problems** most often put forth:

- Inadequately executed welds
- Pre-existent cracks in the weldments
- Residual stresses in the joint resulting from the welding and construction process
- Use of inappropriate weld material, preparation, process and heat treatment
- Through-thickness tension failure of the column flanges
- Fundamental problems with the joint configuration.






# The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps


January 16-17, 2014  
Los Angeles, CA


## Revisiting W1 Indications


### W1s: How Were They Detected?













**Acceptable**

**Difficult** to distinguish with UT between an acceptable weld with backing left in place and a weld with a root crack




**Crack in root**




**Pre-existing crack**

**Impossible** to distinguish with UT whether a crack is pre-existing, or due to earthquake




**Earthquake crack**




**Good weld**







**Crack in weld**




**Crack in fusion zone**




**Crack in HAZ**




**Incomplete fusion**




**Lamellar tear**



Crack in  
weld




Crack in  
fusion zone



Crack in  
HAZ


**All could be identified as W1 in inspection reports**




Incomplete  
fusion




Lamellar  
tear




Good  
weld



Crack in  
weld




Crack in  
fusion zone



Crack in  
HAZ


The solutions to these problems are **very different**



Incomplete  
fusion



Lamellar  
tear



Good  
weld



# The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps

January 16-17, 2014  
Los Angeles, CA

---

## Revisiting W1 Indications


### W1s: Did They Cause the Northridge Fractures?




# FEMA 267

## Interim Guidelines: Evaluation , Repair, Modification and Design of Welded Steel Moment Frame Structures


August 1995






## INTRODUCTION Background

Investigators initially identified a number of factors which may have contributed to the initiation of fractures at the weld root including: notch effects created by the backing bar...substandard welding...and potentially, pre-earthquake fractures resulting from initial shrinkage of the highly restrained weld during cool-down.



## INTRODUCTION Background

Such problems could be minimized in future construction, with the application of appropriate welding procedures and more careful exercise of quality control during the construction process. However, it is now known that these were not the only cause of the fractures which occurred.



## **DAMAGE CLASSIFICATION**

### **Weld Damage, Defects and Discontinuities**

Type W1 is the single most commonly reported non-conforming condition, representing more than 80 per cent of the total damage reported.





Figure 3-4 Types of Weld Damage





Table 3-4 Types of Weld Damage, Defects and Discontinuities


Type	Description
W1	Weld root indications
W1a	Incipient indications – depth , 3/16” or $t_f/4$ ; width $< b_f/4$
W1b	Root indications larger than that for W1a
W2	Crack through weld metal thickness
W3	Fracture at column interface
W4	Fracture at girder flange interface
W5	UT detectable indication – non-rejectable



## DAMAGE CLASSIFICATION

### Weld Damage, Defects and Discontinuities


Some engineers believe that type W1a indications are not earthquake damage at all, but rather, previously undetected defects from the original construction process. A W1b indication is one that exceeds these limits but is not clearly characterized by one of the other types. It is more likely that W1b indications are the result of the earthquake than the construction process.



## INTRODUCTION Background


Some engineers, with knowledge of fracture mechanics, have suggested if materials with adequate toughness are used, and welding procedures are carefully specified and followed, adequate reliability can be obtained from the traditional connection details.





## INTRODUCTION Background

Others believe that the conditions of high tri-axial restraint present in the beam flange to column flange joint (Blodgett—1995) would further prevent ductile behavior of these joints regardless of the procedure used to make the welds. Further they point to the important influence of the relative yield and tensile strength of beam and column materials, and other variables that can affect connection behavior.



## INTRODUCTION

### Background

To date, there has not been sufficient research conducted to resolve this issue.



# The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps

January 16-17, 2014  
Los Angeles, CA

---

## Revisiting W1 Indications

**W1s: What Did The SAC Investigations  
Learn About Them?**



Report No. SAC/BD-99/10

Paret

**Clarifying the Extent of Northridge-Induced  
Weld Fracturing; Examining the Related Issue  
of UT Reliability**

**CONCLUSIONS**

## **Clarifying the Extent of Northridge-Induced Weld Fracturing; Examining the Related Issue of UT Reliability**


### **CONCLUSIONS**

1. W1's are a result of poor welding and inspection practices during construction, not a result of earthquake ground motions.

## **Clarifying the Extent of Northridge-Induced Weld Fracturing; Examining the Related Issue of UT Reliability**


### **CONCLUSIONS**

2. Ultrasonic inspection as normally employed by testing laboratory personnel **is not a reliable inspection technique** for identifying defects in the roots of welded full penetration “T” joints with backing.




**Acceptable**

**Difficult** to distinguish with UT between an acceptable weld with backing left in place and a weld with a root crack




**Crack in root**

“Ultrasonic Inspection...is **not a reliable inspection technique** for identifying defects in the roots of welded full penetration “T” joints with backing.”



**Acceptable**



**Crack in root**



## **Clarifying the Extent of Northridge-Induced Weld Fracturing; Examining the Related Issue of UT Reliability**

### **CONCLUSIONS**


3. The extent of earthquake damage to WSMF buildings is substantially less than has previously been reported.

## Clarifying the Extent of Northridge-Induced Weld Fracturing; Examining the Related Issue of UT Reliability

However, assorted anecdotal evidence suggested that W1's might not be earthquake related at all. For example, a number of samples of W1b's trepanned from welded connections and examined in the laboratory were determined to contain only areas of nonfusion and slag, without any crack extension or other potentially earthquake-related conditions.


**Clarifying the Extent of Northridge-Induced  
Weld Fracturing; Examining the Related Issue  
of UT Reliability**

Figure 6 Distribution of W1's and non-W1's in City of Los Angeles Inventory




**Clarifying the Extent of Northridge-Induced  
Weld Fracturing; Examining the Related Issue  
of UT Reliability**

Figure 6 Distribution of W1's and non-W1's in City of Los Angeles Inventory




**Clarifying the Extent of Northridge-Induced  
Weld Fracturing; Examining the Related Issue  
of UT Reliability**

Figure 6 Distribution of W1's and non-W1's in City of Los Angeles Inventory




From SAC/BD-99/10

Figure 1. Polished and Etched  
Weld Sample with W1



**Clarifying the Extent of Northridge-Induced  
Weld Fracturing; Examining the Related Issue  
of UT Reliability**

Figure 2. Location most often defined for W1's by ultrasonics



**Clarifying the Extent of Northridge-Induced Weld Fracturing; Examining the Related Issue of UT Reliability**

Figure 7. Cumulative Occurrence of Non-W1's in City of Los Angeles Inventory






Figure 7. Cumulative Occurrence of Non-W1's in City of Los Angeles Inventory




Figure 7. Cumulative Occurrence of Non-W1's in City of Los Angeles Inventory




Figure 7. Cumulative Occurrence of Non-W1's in City of Los Angeles Inventory





Figure 7. Cumulative Occurrence of Non-W1's in City of Los Angeles Inventory




**Clarifying the Extent of Northridge-Induced Weld Fracturing; Examining the Related Issue of UT Reliability**

Figure 6 Distribution of W1's and non-W1's in City of Los Angeles Inventory

~~66 buildings~~

**CAVEAT:**  
These data are based on LA inventory of inspected buildings.



~~24 buildings~~

General **ratios** might apply (1/3<sup>rd</sup>-1/3<sup>rd</sup>-1/3<sup>rd</sup>)

~~48 buildings~~

Building **numbers** do not apply outside data base

~~71 buildings~~

## Clarifying the Extent of Northridge-Induced Weld Fracturing; Examining the Related Issue of UT Reliability

Therefore, in the general region of strongest ground shaking only 24 buildings (11% of the total sample) were found to have more than 10% of their connections damaged by the earthquake.....the scope of the “welded moment frame problem”—previously characterized as having results in many scores of severely damaged buildings—appears to be greatly reduced.”



# The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps

January 16-17, 2014  
Los Angeles, CA

---

## Revisiting W1 Indications

**W1s: What Was Done To Eliminate Them?**



# The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps

January 16-17, 2014  
Los Angeles, CA

---

## Revisiting W1 Indications


**W1s: What Was Done To Enable Better  
Detection of Them?**




A piece of blue textured paper with a large, irregular tear. The paper is placed on a white background. The tear is jagged and runs vertically through the center of the paper. The paper has a fine, fibrous texture. The lighting is bright, casting a shadow to the right of the paper.


**Likely a W4**



A photograph of a blue textured material, possibly a book cover or endpaper, with a white measurement line and text indicating a width of 1-5/8 inches (1.625 inches, 41 mm). The material has a fibrous texture and a small tear at the top edge. The measurement is taken across the width of the material, with a horizontal line at the top and a vertical line at the bottom, both ending in arrows pointing towards each other. The text is centered below the measurement line.


**1-5/8"**  
**(1.625", 41 mm)**





2


1



**Under the web**

**Incomplete fusion to steel backing**

**1/4"**  
**[6 mm]**



**AWS D1.1-94**

Structural Welding Code--  
Steel

ANSI/AWS D1.1-94  
An American National Standard

1994

**Structural  
Welding Code**  


---

**Steel**



AMERICAN WELDING SOCIETY





## 4.14 Procedures for Gas Metal Arc and Flux Cored Arc Welding with Single Electrode

### 4.14.1.5 Flux Cored Arc Welding

The thickness of the weld layers in groove welds, except root and surface layers, shall not exceed  $1/4$  in (6 mm).

**AWS D1.1-96**

Structural Welding Code--  
Steel






## Table 3.7 Prequalified WPS Requirements


**Table 3.7  
Prequalified WPS Requirements<sup>f</sup> (see 3.7)**

Variable	Position	Weld Type	SMAW	SAW <sup>d</sup>			GMAW/ FCAW <sup>g</sup>
				Single	Parallel	Multiple	
Maximum Root Pass Thickness <sup>d</sup>	Flat	All	3/8 in [10 mm]	Unlimited			3/8 in [10 mm]
	Horizontal		5/16 in [8 mm]				5/16 in [8 mm]
	Vertical		1/2 in [12 mm]				1/2 in [12 mm]
	Overhead		5/16 in [8 mm]				5/16 in [8 mm]

In 2006, for prequalified WPSs, the maximum root pass thickness is now 3/8 in [10 mm]




B-1  
RD FLR.




# **FEMA 353**

## Recommended Specification and Quality Assurance Guidelines for Steel Moment-Frame Construction for Seismic Applications



July 2000





## 4.1.2 Moment Connection Joints Requiring Removal of Backing Bars


Backing bars shall be removed from the joint when required on the design drawings. Following removal of backing, the root pass shall be backgouged to sound metal, and backwelded.







































**Would an erector really do that?**


**Only once!**



**UT should easily detect this region**

# Benefits of Backing Removal






## Benefits of Backing Removal

- Eliminates notch created by backing


## Benefits of Backing Removal

- Eliminates notch created by backing
- Eliminates root discontinuities (cracks, incomplete fusion, slag)



## Benefits of Backing Removal


- Eliminates notch created by backing
- Eliminates root discontinuities (cracks, incomplete fusion, slag)
- Contouring fillet “softens” the 90° intersection






## Benefits of Backing Removal

- Eliminates notch created by backing
- Eliminates root discontinuities (cracks, incomplete fusion, slag)
- Contouring fillet “softens” the 90° intersection
- UT inspection results are easier to interpret





## 4.8 Welding Sequence for Moment Connection of Bottom Beam Flange

When welding the bottom flange of the column flange of welded moment-resisting connections, the following sequence shall be followed:

1. When welding from side A (one side of the beam), the root pass shall begin beyond the center of the joint on Side B, reaching past the beam web (or web plate, for FF connections) through the weld access hold (or opening, for FF connections). After the arc is

**AWS D1.8:2009**

Seismic Welding  
Supplement


AWS D1.8/D1.8M:2009  
An American National Standard

**Seismic  
Welding  
Supplement**




American Welding Society





## 6.7 Removal of Backing and Weld Root Treatment

When fusible (steel) backing is required to be removed, removal shall be by air carbon arc cutting (CAC-A), plasma arc gouging (PAC-G), grinding , chipping , or thermal cutting. The process shall be controlled to minimize errant gouging. After backing removal (both for steel and nonfusible backing), the weld root shall be backgouged to sound metal. Backgouged joints shall be filled with weld metal as necessary, to achieve at



## 6.14 Bottom Flange Welding Sequence

Complete joint penetration groove welds of beam bottom flanges to column flanges, or to continuity plates, using weld access holes shall be sequenced as follows:

- (1) As far as is practicable, starts and stops shall not be directly under the beam web
- (2) Each layer shall be complete across the full width



# **The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps**

January 16-17, 2014  
Los Angeles, CA

---

## **Revisiting W1 Indications**

### **Changes to the Northridge Record**

## Changes to the Northridge Record

**1994**

**Problem:**

W1 incipient cracks



**2014**

**Problem:**

Incomplete fusion

**Solutions:**

preheat  
slow cooling  
postheat  
peening  
welding sequence  
process change



**Solutions:**

root pass thickness  
bottom flange welding  
sequence  
backgouging



# The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps

January 16-17, 2014  
Los Angeles, CA

## Changes to the Northridge Record

**1994**

**Assumption:**  
UT is effective at  
detecting weld root  
problems



**2014**

**New Practice:**

- Remove backing
- Backgouge to sound metal
- Apply contouring fillet
- UT with backing removed





# The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps

January 16-17, 2014  
Los Angeles, CA

## Changes to the Northridge Record

**1994**

**Problem Description:**

Hundreds of damaged buildings

60-80% damaged connections

2/3<sup>rd</sup> of inspected buildings were damaged



**2014**

**Problem Description:**

Widespread original workmanship and inspection issues

Concentrated earthquake damage

1/3<sup>rd</sup> of inspected buildings were damaged



# The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps

January 16-17, 2014  
Los Angeles, CA

## Recommendations

- Use welded steel SMRFs with confidence
- Use AISC Seismic Specs
- Use AISC CPRP Connections
- Avoid special welding-related job requirements except in special situations



# The 1994 Northridge Earthquake: Impacts, Outcomes, and Next Steps

January 16-17, 2014  
Los Angeles, CA

---

## Revisiting W1 Indications